INSPECTION REPORT FOR MOTORABLE WORK

Name of PIUs:- RKID WORKS DIVISION, NANGACHHIYA	
Name of Block / Road :- NARRY ANDUR 1041 - CHIO 11 BISHANDOR 1	ro yusuffur
A. For Road	
1. Damage Location / Chainage: 700 -100, 1000 -1300	
2. Damage Length: 521.0 m	
3. Nature of Damage (length wise) (i) Breach : 25th	
(ii) Crust Damage :- 49617	
(iii) Only Flank Damage	
whether traffic fully/Partialily obstructed - Fully obstructed	
4. Details of Restoration;	
(i) Material Being Used in Restoration: Brick Bak	
(ii) Equipment / Tools being Used in Restoration Works: Front end 20	aber, Roller
(iii) Restored length In open Area: 521.0 m	
In habitation Area:-	
(iv) if Restoration work done in habitation Area give Reason :	
B. For Bridge (Size of Bridge / Culvert)	
1. Damage Location / Chainage : —	
2. No. of Span Damage :	
3 Length of Span —	
4 Nature of Damage (Pier / Abutment/Wing wall/Approach Road Damage	e) _
5. Details of Restoration:	
(i) Material Being Used in Restoration :	
(ii) Equipment / Tools being Used in Restoration Works : —	
(iii) Restored length In open Area:-	
In habitation Area:-	
Overall Grade of Restoration Work (Satisfactory / Unsatisfactory)	sfactory.

Santorhuyaniani 19111124 (hum. 1921)
141111024 19111124 Et

Signture of Inspector

(Officail Seal) eer

RWD Works Division

BANKA-1