

INSPECTION REPORT FOR MOTORABLE WORK

Name of PIUs :- EE RWA Works Division Anania

Name of Block/Road :- Jakihat / Dhuna - Masuria Via Majgawa Part A

A. For Road

1. Damage Location/Chainage :- 0.9 km, 1.1 km

2. Damage Length :- 29.7 mtr

3. Nature of Damage (Length Wise)

(i) Breach :-	Breach Damage
(ii) Crust Damage :-	Crust Damage
(iii) Only Flank Damage :-	—

whether traffic fully/Partially obstructed :- fully

4. Details of Restoration :-

(i) Material Being Used in Restoration :- local sand, bamboo piling, Ec bags, Bricks

(ii) Equipment/Tools Being Used in Restoration Works :- Tractor with trolley, JCB, Roller etc

(iii) Restored Length

In open Area :-	open Area
In habitation Area :-	

(iv) If Restoration work done in habitation Area give Reason :-

B. For Bridge (Size of Bridge/Culvert)

(1) Damage Location/Chainage :-

(2) No. of Span Damage :-

(3) Length of Span :-

(4) Nature of Damage (Pier/Abutment/Wing Wall/Approach Road Damage) :-

(5) Details of Restoration :-

(i) Material Being Used in Restoration :-

(ii) Equipment/Tools Being Used in Restoration Works :-

(iii) Restored Length :-

Overall Grade of Restoration work (Satisfactory/Unsatisfactory) :- Satisfactory

[Signature]
2/11/24

[Signature]
2/11/24

[Signature]
2/11/24
Signature of Inspector
(Official Seal)