

Inspection Report For Flood Damage Work

- 1 Name of PIUs: Girhaganj-2
- 2 Name of Block/Road: Hardeys To Bhagwanpur / Baiduthpur.
- For Road
- 1 Damage Location / Chainage: 3020, to 3045 M, 5040 to 5065 M, 5380 M to 5410 M
- 2 Damage Length: 115 M 700 to 7035 M
- 3 Nature of Damage: Heavy Rain / Flood
- 4 Details of Restoration Works:
- i. Material being used in Restoration Works: Brick Bats
- ii Equipments / Tools being used in Restoration Works: JCB, Kales, Tractors, Trolis etc.
- iii Procedure taken up in Restoration Works: Yes
- iv Restored Length: 115 M

For Bridge

1 Damage Location / Chainage:

2 Damage Length:

3 Nature of Damage:

4 Details of Restoration Works:

- i. Material being used in Restoration Works:
- ii Equipments / Tools being used in Restoration Works:
- iii Procedure taken up in Restoration Works:
- iv Restored Length:

N/A.
work found satisfactory.
13/11/24

EXECUTIVE ENGINEER
RURAL WORKS DEPARTMENT
WORKS DIVISION SIWAN-2

JE
15/9/24

AE
15.09.24

EE
15.09.24

S.E