

## Inspection Report For Flood Damage Work

Date:

1 Name of PIUs:

Gopalganj-2

2 Name of Block/Road:

Deasaberi To Bisthi / Baikunthpur

A For Road

1 Damage Location / Chainage:

24954 to 25104

2 Damage Length:

15 m

3 Nature of Damage:

Heavy Rain / Flood

4 Details of Restoration Works:

i. Material being used in Restoration Works:

Brick Bats

ii Equipments / Tools being used in Restoration Works:

JCB, Roller, Tractor, Pickle etc.

iii Procedure taken up in Restoration Works:

Yes

iv Restored Length:

15 m

B For Bridge

1 Damage Location / Chainage:

2 Damage Length:

3 Nature of Damage:

4 Details of Restoration Works:

i. Material being used in Restoration Works:

ii Equipments / Tools being used in Restoration Works:

iii Procedure taken up in Restoration Works:

iv Restored Length:

N/A work found satisfactory

13/11/2017  
EXECUTIVE ENGINEER  
RURAL WORKS DEPARTMENT  
WORKS DIVISION SIWAN-2

JE

24.11/24

AE

24.11/24

EE

24.11/24

S.E