

## Inspection Report for Flood Damage Work

1. Name of PIUs : R.W.D Kishanganj-1  
2. Name Of Block / Road : RCC Bridge at LO 47 - LO 46 to Musaidanga,  
under Bahadurganj Block

### A. For Road

1. Damage Location / Chainage :  
2. Damage Length : 0.044 Km  
3. Nature Of Damage :  
4. Details Of Restoration :  
i) Material Being Used In Restoration : Bamboo, Local Sand, Bricks Bats, E.C. Bags  
ii) Equipment / Tools Being Used In Restoration Works : Tractor, Bamboo Pilling Machine.  
iii) Procedure Taken Up In Restoration Works :  
iv) Restored Length : 0.044 Km

### B. For Bridge

1. Damage Location / Chainage :  
2. Damage Length :  
3. Nature Of Damage :  
4. Details Of Restoration :  
i) Material Being Used In Restoration :  
ii) Equipment / Tools Being Used in Restoration Works :  
iii) Procedure Taken Up In Restoration Works :  
iv) Restored Length : 0.044 Km

*Kunal*  
12/11/24  
JE

*sw*  
12/11/24  
AE

*gof 20/11/24*  
Signature of Inspector  
(official seal)