

Inspection Report for Flood Damage Work

1. Name of PIUs : RWD Kishanganj-2

2. Name Of Block / Road : Dighalbank/ Rec Bridge at Tedhgechh Badubani road
Ula Mathyari

A. For Road

1. Damage Location / Chainage :

2. Damage Length :

3. Nature Of Damage :

4. Details Of Restoration :

i) Material Being Used In Restoration ::

ii) Equipment / Tools Being Used In Restoration Works :

iii) Procedure Taken Up In Restoration Works :

iv) Restored Length :

B. For Bridge

1. Damage Location / Chainage : Near Guahati Bridge

2. Damage Length : 76.00 m

3. Nature Of Damage :

4. Details Of Restoration :

i) Material Being Used In Restoration : Bamboo Pile, Earthwork, Ec Bags, MC, Brickbat

ii) Equipment / Tools Being Used In Restoration Works : Tractor, JCB

iii) Procedure Taken Up In Restoration Works ::

iv) Restored Length : 76.00 m


Signature of Inspector
(official seal)