

## Inspection Report for Flood Damage Work

1. Name of PIUs : RWD Kishanganj-2

2. Name Of Block / Road : Dighalbonk / To3-To3 To Dhargara (Rec Bridge at To3-To3 To Dhargara at CH:- 9.200 km

### **A. For Road**

1. Damage Location / Chainage : CH:- 9.200 km

2. Damage Length : 12.00 m

3. Nature Of Damage :

4. Details Of Restoration :

i) Material Being Used In Restoration : Bambo Pile, Earthwork, EC Bags

ii) Equipment / Tools Being Used In Restoration Works : Bambo Pile Machine, JCB

iii) Procedure Taken Up In Restoration Works :

iv) Restored Length : 12.00 m

### **B. For Bridge**

1. Damage Location / Chainage :

2. Damage Length :

3. Nature Of Damage :

4. Details Of Restoration :

i) Material Being Used In Restoration :

ii) Equipment / Tools Being Used in Restoration Works :

iii) Procedure Taken Up In Restoration Works ::

iv) Restored Length :

  
**Signature of Inspector**  
(official seal)