INSPECTION REPORT FOR MOTORABLE WORK				
Date:- 98111129				
1 Name of PIUs:-	Priyaranjan Das (Executive Engineer Saharsa)			
Name of Block/Road :-	Construction of HL Bridge 2x18.75 m at Cr-9 in Bardh Maharas Pradhannanti Sadak to Ranswarup singh he ghar tak Road			
A For Road Ranswarup Singh Ke ghar talk kuna				
1 Damage Location/Chainage :-	N/A			
2 Damaga Langth	N/A	mt.		
2 Damage Length :- 3 Nature of damage	2 amage 2 anger.			
(Length Wise):- (ii) Crust Diamage :- N/A				
(Bengen Wise)		(iii) Only Flank Diamage:- N/A		
Whether traffic fully/Partialiy obstructed:- Fully obstructed				
4 Details of Restoration Works :-		<u> </u>	-	
i Material being used in Restortion works:- N/A				
ii Equipments/Tools being used in Restoration works:- N/A				
iii Restored Length:-	- Trestoration works	In open Area:-	N/A mt.	
m Restored Length.		In Habitation Area:-	N/A mt.	
iv If Restoration work done in Hbitation Area Give Reason:-				
B. For Bridge		141 - 10	0	
1 Damage Location/Chainage:- A, Side Approach Road				
2 Damage Length: 39 M				
3 Nature of damage:- Approach road At A, Side was badly dange				
4 Details of Restoration Works:- Brick bat filling				
i Material being used in Restortion works:- Brick Bat				
ii Equipments/Tools being used in Restoration works: Tractor TCB Me Chine				
iii Procedure taken up in Restoration works:- Restoration work by Brille Sul filly				
iv Restored Length:- 3	9 M			
Overall Grade of Restoration work	/Satisfactory/Unsatisfac	ctory):- Satisfactory		
Overall Grade of Restoration work	(Satisfactory) Onsurers	Sign	nature of Inspection (Of (Name of inspector)	or nent
			Executive Engines paring Rural Wo Warks Division, Sahar	sa