INSPEC	TION REPORT FOR MOTORABLE WORK
Date:- 28/11/24	
1 Name of PIUs:-	Priyaranjan Das (Executive Engineer Saharsa)
Name of Block/Road :-	Construction of RCC Posidge at 6th km Lu71-To3 To Khara Mushari (VR30)
A. For Road	
1 Damage Location/Chainage :- N	/A
2 Down I angth:	N/A mt.
2 Damage Length :-  3 Nature of damage	(i) Breach :- N/A
(Length Wise):-	(ii) Crust Diamage :- N/A
(===g==,	(iii) Only Flank Diamage:- N/A
Whether traffic fully/Partialiy	T II 1 toward
4 Details of Restoration Works :-	
i Material being used in Restor	tion works:-
ii Equipments/Tools being used in	
iii Restored Length:-	In open Area:-
	In Haditation Area.
iv If Restoration work done in Hbit	tation Area Give Reason:-
B. For Bridge	
1 Damage Location/Chainage :-	A, & Az Side Approach Rosal
2 Damage Length :- 35	1-00 M broach road Was badly domaged Brick bat filling in A, & Az Sixe
3 Nature of damage:-	would wond with saving a majer
4 Details of Restoration Works :-	Brick bat filling in 14,8 hr side
i Material being used in Restortion	n works:- Brick Bat  Restoration works:- Tractor & JCB Machine
ii Equipments/Tools being used in	nestoration to be projet but fill
iii Procedure taken up in Restoratio	mt.
iv Restored Length: 3 7 A	1
Occupil Crade of Restoration work (S	atisfactory/Unsatisfactory):- Satisfactory
Overall Glade of Restoration was a	Bus 124
	Signature of Inspection(Official Seal)
	(Name of inspector)
	Executive Engineer  Rural Works Department
	Warks Division, Saharas