INSPE	CTION REPORT	FOR MOT	ORABLE WORK	(
Date:- 27-111124				
1 Name of PIUs:-	Priy	Priyaranjan Das (Executive Engineer Saharsa)		
Name of Block/Road :-	To3 To	KHARA	MUSHARI (VR38)
A. For Road				
1 Damage Location/Chainage :-	0.68 KM, 0.75 KM 330 KM, 3.71 KM	M, 3.98 KM M, 3.98 KM	045KM,1.329K 4.85 KM, 4.45KM,	M, 1.523 KM, 2.708 KH 5.5 KM, 5.51 KM, 5.62 KA 8.3 KM
2 Damage Length: 228.0	OM	mt.	,	,
3 Nature of damage	(i) Breach :-	228 M		
(Length Wise) :-	(ii) Crust Diam	iage :-		
	(iii) Only Flank	k Diamage:-		
Whether traffic fully/Partia	liy obstructed:-		Fully obstructed	
4 Details of Restoration Works :	-			
i Material being used in Resto		Brick Bat		
ii Equipments/Tools being used i	n Restoration works :-		Tractor,JCB Machine	
iii Restored Length:- 2	28 M	In open Area:-	228·W M	mt.
		In Habitation		mt.
iv If Restoration work done in H	oitation Area Give Rea	son:-	N/A	
B. For Bridge				
1 Damage Location/Chainage :-			N/A	
2 Damage Length :-			N/A	
3 Nature of damage :-			N/A	
4 Details of Restoration Works:-			N/A	
i Material being used in Restortion works:-			N/A	_
ii Equipments/Tools being used in Restoration works :-			N/A	
iii Procedure taken up in Restoration works:-			N/A	
iv Restored Length:-			mt.	
Overall Grade of Restoration work	Satisfactory/Unsatisfac	ctory):- Satisfac	tory	
				f Inspection(Official Seal) e of inspector)
			Evecu	tive Engineer
			Rural W	orks Department
				hivision Saharsa