IN	SPECTION REPOR	T FOR MOTORAB	LE WORK		
Date:- 28 [11]2	4				
1 Name of PIUs:-		Priyaranjan Das (Executive Engineer Saharsa)			
Name of Block/Road :-			ge at Holiye Nale or Koshi Brand Canal (
A. For Road		COK 21K 203 OVE	i hely branchar		
1 Damage Location/Chains	ige:- N/A				
2 Damage Length :-	N/A	mt.			
Nature of damage	(i) Breach :- N	(i) Breach :- N/A			
(Length Wise) :-	(ii) Crust Dian	nage :- N/A			
		k Diamage:- N/A			
Whether traffic fully/Partialiy obstructed:- Fully obstructed					
4 Details of Restoration Wo			-		
i Material being used in F	Restortion works:-		N/A		
ii Equipments/Tools being u	sed in Restoration works :-	N/A			
iii Restored Length:-		In open Area:-	N/A mt.		
		In Habitation Area:-	N/A mt.		
iv If Restoration work done i	n Hbitation Area Give Rea	son:-	N/A		
B. For Bridge					
1 Damage Location/Chainage	:- A, & A2	Side Appro	pach Road		
2 Damage Length :-	34 M	- · · · · · · · · · · · · · · · · · · ·			
3 Nature of damage:-	toproach to	hel was badl	y danged		
4 Details of Restoration Work	is: Bamboo pil	ing, Band bag	g danged filling & Brick word ag, Bamboo		
i Material being used in Resto	ortion works:- 1571 U.C.	Tractor, JCB	Machine, San,		
ii Equipments/Tools being use		1 - 6 61 .	Approach road		
ii Procedure taken up in Resto	ration works:- Re	JOHNANDE !	mt.		
v Restored Length:- 3	4 M				
erall Grade of Restoration wo	-l. (Catisfactory/I Insatisfact	rory):- Satisfactory			
erall Grade of Restoration wo	K (Satisfactory) Offsatisfact	,			
			111124		
			Signature of Inspection(Official Se		
			(Name of inspector)		
			Executive Engineer		
			Rural Wol. partment		