INSPECTION REPORT FOR MOTORABLE WORK

ame of PIUs :- E	E PLAN	IW) SIKH	arna (Bha	, (e)	
	- KW17	thorasohan	Qa Kuliya	Pall No	ahar chubk
ame of Block/Road :-	(azarite m	159 Kunga		
For Road	r	arriva.			
Damage Location/Chai	nage :-		· · ·		
Damage Length :-	0.085 1	1,			
Nature of Damage (Len		(i) Prouch :-		1.8Ckm	
		(ii) Crust Dama	ige :- 0 · (701 (0.	
		(iii) Only Flank	Damage :-	1 1	
hether traffic fully/Part	ialiy obstruc	eted:-	/ Obest	nedead	
			1/1/2	sal1	
TId:	- Dectoration	on: Back bas	D) gramano		
in Englished Rei	ing Used in	Restoration Wor	ks: JCB	tractor	Collex
i) Equipment/Tools Being Used		In open Area:	0.0	Jkm.	
ii) Restored Length		In habitation A	rea :-		
v) If Restoration work	I in hohi	itation Area give	Reason:-	_	
v) If Restoration work	done ili ilab	ulvert)			
For Bridge (Size of	Bridge/C		-		
Damage Location/Ch	nainage:-				
2) No. of Span Damage					
3) I enoth of Span :-					
- FDamage (F	ier/Abuttme	ent/	, , · _	_	
Ving Wall/Approach Ro	oad Damage	e):- 			
5) Details of Restoratio	in Restorați	on :-			
) Material Being Used	in restorain	Restoration Wo	rks :-	_	and the second
ii) Equipment/Tools Be	ing Usea in	Kestotation (_	and the second
iii) Restored Length :-					
			// I tiofoo	toru) :- M	Le la dans
)verall Grade of Rest	oration wor	rk (Satisfactor)	Onsaustac	COLY) - Sec	19 Jane
		J	•	Winese	er'
				A3	10/01/24
				ure of Inspe	TOJO
Dod-			iondal (Of	ficial Seal)	
7		90.	(24		
30.11.24.			E Dhak	(2)	
A.F. Ranaul.		,	T.	• 0	