

INSPECTION REPORT FOR MOTORABLE WORK

Name of PIUs :- Vikas Samiti, EE RWD Area

Name of Block/Road :- Haridolvi, 81144 to 144000/201

A. For Road

1. Damage Location/Chainage :- 4-10m

2. Damage Length :- 86m

3. Nature of Damage (Length Wise)

(i) Breach :- 22m

(ii) Crust Damage :-

(iii) Only Flank Damage :- 64m

whether traffic fully/Partially obstructed :- fully obstructed

4. Details of Restoration :-

(i) Material Being Used in Restoration :- Brick Bats, Sand Bags, Bamboo

(ii) Equipment/Tools Being Used in Restoration Works :- JCB, Tractor with trolley

(iii) Restored Length

In open Area :- open Area

In habitation Area :-

(iv) If Restoration work done in habitation Area give Reason :-

B. For Bridge (Size of Bridge/Culvert)

(1) Damage Location/Chainage :-

(2) No. of Span Damage :-

(3) Length of Span :-

(4) Nature of Damage (Pier/Abutment/
Wing Wall/Approach Road Damage) :-

(5) Details of Restoration :-

(i) Material Being Used in Restoration :-

(ii) Equipment/Tools Being Used in Restoration Works :-

(iii) Restored Length :-

Total Estimated cost Rs 12.32 lac.

Overall Grade of Restoration work (Satisfactory/Unsatisfactory) :- Satisfactory

[Signature]
28/11/24
AS
chake

[Signature]
28/11/24
AS
chake

[Signature]
28.11.24
Signature of Inspector
(Official Seal)