

# INSPECTION REPORT FOR MOTORABLE WORK

Date:- 27/11/24

|                                                                                |                                      |                                                                |          |
|--------------------------------------------------------------------------------|--------------------------------------|----------------------------------------------------------------|----------|
| 1                                                                              | Name of PIUs :-                      | Priyaranjan Das (Executive Engineer Saharsa)                   |          |
| 2                                                                              | Name of Block/Road :-                | Koshi Bandh 105 RD To Bhetwara Via<br>Lachminiya Middle School |          |
| A. For Road                                                                    |                                      |                                                                |          |
| 1                                                                              | Damage Location/Chainage :-          | 0.85 km, 0.95 km, 1.75 km                                      |          |
| 2                                                                              | Damage Length :-                     | 48 mt.                                                         |          |
| 3                                                                              | Nature of damage<br>(Length Wise) :- | (i) Breach :- 48 M                                             |          |
|                                                                                |                                      | (ii) Crust Damage :-                                           |          |
|                                                                                |                                      | (iii) Only Flank Damage:-                                      |          |
| Whether traffic fully/Partialiy obstructed:-                                   |                                      | Fully obstructed                                               |          |
| 4 Details of Restoration Works :-                                              |                                      |                                                                |          |
| i Material being used in Restortion works:-                                    |                                      | Brick Bat & Sand                                               |          |
| ii Equipments/Tools being used in Restoration works :-                         |                                      | Tractor, JCB Machine                                           |          |
| iii Restored Length :-                                                         |                                      | 48.00 M                                                        |          |
|                                                                                |                                      | In open Area:-                                                 | 48 M mt. |
|                                                                                |                                      | In Habitation Area:-                                           | mt.      |
| iv If Restoration work done in Hbitation Area Give Reason:-                    |                                      | N/A                                                            |          |
| B. For Bridge                                                                  |                                      |                                                                |          |
| 1 Damage Location/Chainage :-                                                  |                                      | N/A                                                            |          |
| 2 Damage Length :-                                                             |                                      | N/A                                                            |          |
| 3 Nature of damage :-                                                          |                                      | N/A                                                            |          |
| 4 Details of Restoration Works :-                                              |                                      | N/A                                                            |          |
| i Material being used in Restortion works:-                                    |                                      | N/A                                                            |          |
| ii Equipments/Tools being used in Restoration works :-                         |                                      | N/A                                                            |          |
| iii Procedure taken up in Restoration works :-                                 |                                      | N/A                                                            |          |
| iv Restored Length :-                                                          |                                      | mt.                                                            |          |
| Overall Grade of Restoration work (Satisfactory/Unsatisfactory):- Satisfactory |                                      |                                                                |          |

Signature of Inspection (Official Seal)  
(Name of inspector)  
**Executive Engineer**  
**Rural Works Department**  
**Works Division, Saharsa**

