INSPECTION REPORT FOR MOTORABLE WORK				
Date:- 25/11/24				
1 Name of PIUs:-	Priyaranjan Das (Executive Engineer Saharsa)			
Name of Block/Road :-	KOSHI Bandh Pakki Sadak to Kutwelija Nago Choudhari House			
A. For Road				
1 Damage Location/Chainage :-	0.20KM, 0.	550 KM		
2 Damage Length :-	19 8 mt.			
3 Nature of damage	(i) Breach :- 198			
(Length Wise):-	(ii) Crust Diamage :-			
	(iii) Only Flank Diamage:-			
Whether traffic fully/Partiali	Fully obstructed			
4 Details of Restoration Works :-				
i Material being used in Restor		Brick Bat & Sand		
ii Equipments/Tools being used in Restoration works :-		Tractor,JCB Machine		
iii Restored Length:-		In open Area:- 9	78	mt.
		In Habitation Area:-		mt.
iv If Restoration work done in Hbi	on:-	N/A		
B. For Bridge				
1 Damage Location/Chainage :-	1	N/A		
2 Damage Length :-		N/A		
3 Nature of damage :-		N/A		
4 Details of Restoration Works :-		N/A		
i Material being used in Restortion works:-		N/A		
ii Equipments/Tools being used in Restoration works:-		N/A		
iii Procedure taken up in Restoration works:-		N/A		
iv Restored Length:-		0.00 mt.		
	77 . · · · ·			
Overall Grade of Restoration work (S	atisfactory/Unsatisfac	tory):- Satisfactory		
			(Name of	11)24 spection(Afficial Seal) finspector)ment
			AASILIO DI	