## INSPECTION REPORT FOR MOTORABLE WORK

Name of Block/Road - Balsi / Bara Rahera to Bara Pahua chandrabhus	
	Sachiv He Whor Tall
A. For Road	) J.
1. Damage Location/Chainage:- 6.7	50 KIY
2. Damage Length:- 12Mt	
3. Nature of Damage (Length Wise)	(i) Breach:- 1200 MY
	(ii) Crust Damage :-
	(iii) Only Flank Damage :
whether traffic fully/Partialiy obstructed:	fully obstructed
4. Details Of Restoration :-	
(i) Material Being Used in Restoration :-	Brick Beds.
(ii) Equipment/Tools Being used in Resto	In Open Area 12-00147
(iii) Restoration Length	In Open Area 12-00 14 h
	In Habitation Area:-
B. For Bridge (Size Of Bridge/Cu	lvert)
1. Damage Location/Chainage:-	/!
2. No. Span Damage :-	
3. Length of Span :-	/
4. Nature of Damage (Pier/Abuttment/ Wing Wall/Approach Road Damage)	
5. Datails of Restoration:-	
(i) Material Being Used in Restoration:-	
(ii) Equipment/Tools Being used in Restor	ration Work :-
(iii) Restored Length :-	
	actory/Unsatisfactory):- Satisfecting
Overall Grade of restoration Work (Satisfa	actory/Unsatisfactory):-

Signature Of Inspection (Official Seal) असंबद्ध कार्यपालक अभियंता ग्रामीण कार्य विभाग, कार्य प्रमंडल, पूर्णियाँ