

INSPECTION REPORT FOR MOTORABLE WORK

Name of PIUs :- BARSOI

Name of Block/Road :- BARSOI BISHOR HAT PWUSY TO DENURA PARA

A. For Road

1. Damage Location/Chainage :-

2. Damage Length :- 0.189 M

3. Nature of Damage (Length Wise) (i) Breach :- 0.189 m

(ii) Crust Damage :- ☒

(iii) Only Flank Damage :-

whether traffic fully/Partialiy obstructed :- fully obstructed.

4. Details of Restoration :-

(i) Material Being Used in Restoration :- Bricks Bats

(ii) Equipment/Tools Being Used in Restoration Works :- Truck, S.C.B

(iii) Restored Length

In open Area :- ☒

In habitation Area :-

(iv) If Restoration work done in habitation Area give Reason :-

B. For Bridge (Size of Bridge/Culvert)

(1) Damage Location/Chainage :-

(2) No. of Span Damage :-

(3) Length of Span :-

(4) Nature of Damage (Pier/Abuttment/
Wing Wall/Approach Road Damage) :-

(5) Details of Restoration :-

(i) Material Being Used in Restoration :-

(ii) Equipment/Tools Being Used in Restoration Works :-

(iii) Restored Length :-

Overall Grade of Restoration work (Satisfactory/Unsatisfactory) :- ☒ Satisfactory

29/11/2024
Signature of Inspector
(Official Seal)