

Inspection Report for Flood Damage Work

1. Name of PIUs : R.W.D Kishanganj-I
2. Name Of Block /Road : LO 47 - LO 46 to Musaldanga.

A. For Road

1. Damage Location / Chainage :
2. Damage Length : - 0.015 Km
3. Nature Of Damage :
4. Details Of Restoration :
i) Material Being Used In Restoration : Bamboo, Local sand, Bricks bet. R.C. bags.
ii) Equipment / Tools Being Used In Restoration Works : Tractor, Bamboo piling machine.
iii) Procedure Taken Up In Restoration Works : Manual
iv) Restored Length :

B. For Bridge

1. Damage Location / Chainage :
2. Damage Length :
3. Nature Of Damage :
4. Details Of Restoration :
i) Material Being Used In Restoration :
ii) Equipment / Tools Being Used in Restoration Works :
iii) Procedure Taken Up In Restoration Works :
iv) Restored Length : - 0.015 Km

12/11/24
JH
Shr
12-11-24
KE

01/12/2024/11/24
Signature of Inspector
(official seal)