

INSPECTION REPORT FOR MOTORABLE WORK

Name of Road 1042 - Baliga 6031 to Popratol.

Name of Block/Road :- Name of P.D. - E.E R.W.D Barsoi.

A. For Road

1. Damage Location/Chainage :- 1915 M, 2005 M, 2485 M

2. Damage Length :- 0.0564 km

3. Nature of Damage (Length Wise) (i) Breach :- —
(ii) Crust Damage :- ✓
(iii) Only Flank Damage :- ✓

whether traffic fully/Partially obstructed :-

4. Details of Restoration :- Bricks butts.

(i) Material Being Used in Restoration :- Bricks butts.

(ii) Equipment/Tools Being Used in Restoration Works :-

(iii) Restored Length 0.0564 km In open Area :- ✓
In habitation Area :- —

(iv) If Restoration work done in habitation Area give Reason :-

B. For Bridge (Size of Bridge/Culvert)

(1) Damage Location/Chainage :- N/A

(2) No. of Span Damage :- N/A

(3) Length of Span :- N/A

(4) Nature of Damage (Pier/Abutment/
Wing Wall/Approach Road Damage) :- N/A

(5) Details of Restoration :- N/A

(i) Material Being Used in Restoration :- N/A

(ii) Equipment/Tools Being Used in Restoration Works :- N/A

(iii) Restored Length :- N/A

Overall Grade of Restoration work (Satisfactory/Unsatisfactory) :- Satisfactory

M. Jha
25/11/24
JE

Signature of Inspector
(Official Seal)

कायपालक अभियंता
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, बारासोई, कटिहार