

INSPECTION REPORT FOR MOTORABLE WORK

Name of PIUs :-

Alay Kumar

Name of Block/Road :-

Amalabadi/1035-1025 to Channamari

A. For Road

1. Damage Location/Chainage :-

2. Damage Length :- 83 m

3. Nature of Damage (Length Wise)

(i) Breach :- 83 m

(ii) Crust Damage :-

(iii) Only Flank Damage :-

whether traffic fully/Partially obstructed :-

4. Details of Restoration :-

(i) Material Being Used in Restoration :- Brock Salt, Rubbish

(ii) Equipment/Tools Being Used in Restoration Works :- Tractor with tray

(iii) Restored Length 83 m

In open Area :-

In habitation Area :-

(iv) If Restoration work done in habitation Area give Reason :-

B. For Bridge (Size of Bridge/Culvert)

(1) Damage Location/Chainage :-

(2) No. of Span Damage :-

(3) Length of Span :-

(4) Nature of Damage (Pier/Abutment/
Wing Wall/Approach Road Damage) :-

(5) Details of Restoration :-

(i) Material Being Used in Restoration :-

(ii) Equipment/Tools Being Used in Restoration Works :-

(iii) Restored Length :-

Overall Grade of Restoration work (Satisfactory/Unsatisfactory) :- Satisfactory

Signature of Inspector

(Official Seal)

कार्यपालक अभियन्ता
ग्रामीण कार्य विभाग
नगर प्रमुख कारिदार