## INSPECTION REPORT FOR MOTORABLE WORK

INSPECTION REPOR	(I FUR MUTURABLE WORK
Name of PIUs:- EE, RWD	work Dinsion, Kathar
Name of Block/Road :- Mans	sali/ PMGSY lahs9 to Gobra ghat
•	
Damage Location/Chainage :-	4: 25.466053 long: 87.656284
Damage Length: 30.704 +1	4H= 44.70 M
Nature of Damage (Length Wise)	(i) Breach: $30.70977444 = 44.7077$
	(II) Crust Damage
	(iii) Only Flank Damage:-
whether traffic fully/Partially obstruct	ed:- Fully obstructed
Details of Restoration :-	
i) Material Being Used in Restoration	1:- Brick Bals
(ii) Equipment/Tools Being Used in R	estoration Works: - Tractor Trolly Coader, Roller etc.
(iii) Restored Length	In open Area: 30.70 M+14.
	In habitation Area:-
iv) If Restoration work done in habita	ation Area give Reason:- NA
B. For Bridge (Size of Bridge/Cu	lvert) NA
(1) Damage Location/Chainage:-	
(2) No. of Span Damage:-	
(3) Length of Span :-	
(4) Nature of Damage (Pier/Abuttmer Wing Wall/Approach Road Damage)	nt/ :-
(5) Details of Restoration:-	
(i) Material Being Used in Restoration	n :-
(ii) Equipment/Tools Being Used in F	Restoration Works:-
(iii) Restored Length :-	
Overall Grade of Restoration work	(Satisfactory/Unsatisfactory): - Satisfactory
Laurett &	Signature of Inspector (Official Seal)
25/11/My	कार्यपालक अनियन्ता ग्रामीण कार्य विमान

कार्य प्रमंडल कटिहार