

INSPECTION REPORT FOR MOTORABLE WORK

Name of PIUs :- Er. Parveen Kumar Singh (EE RWD WKS DIV Badli)
 Name of Block/Road :- Badli / Toz Sharma To more To Sahidpur

A. For Road

1. Damage Location/Chainage :- 1.850 km

2. Damage Length :- 9.00 mtr

3. Nature of Damage (Length Wise)	(i) Breach :- <u>9.00 mtr</u>
	(ii) Crust Damage :- <u>—</u>
	(iii) Only Flank Damage :- <u>—</u>

whether traffic fully/Partialiy obstructed :- fully obstructed

4. Details Of Restoration :-

(i) Material Being Used in Restoration :- Brick Bats

(ii) Equipment/Tools Being used in Restoration Work :- TCB, Tractor

(iii) Restoration Length	In Open Area <u>9.00 mtr</u>
	In Habitation Area :- <u>—</u>

B. For Bridge (Size Of Bridge/Culvert)

1. Damage Location/Chainage :-

2. No. Span Damage :-

3. Length of Span :-

4. Nature of Damage (Pier/Abuttment/
Wing Wall/Approach Road Damage)


5. Details of Restoration :-

(i) Material Being Used in Restoration :-

(ii) Equipment/Tools Being used in Restoration Work :-

(iii) Restored Length :-

Overall Grade of restoration Work (Satisfactory/Unsatisfactory) :- Satisfactory


 Signature Of Inspection
 (Official Seal)
 असंबद्ध कार्यपालक अभियंता
 ग्रामीण कार्य विभाग,
 कार्य प्रमंडल, पूर्णियाँ