

INSPECTION REPORT FOR MOTORABLE WORK

Name of PIUs :- EE RIND WORK Division Baisi

Name of Block/Road Amour / Mangaltendu More to Belgachhi

A. For Road

1. Damage Location/Chainage :- 0.900 km, 2.100 km

2. Damage Length :- 26.00 m

3. Nature of Damage (Length Wise)

(i) Breach :- 26.00 m

(ii) Crust Damage :-

(iii) Only Flank Damage :-

whether traffic fully/Partialiy obstructed :- Fully obstructed,

4. Details Of Restoration :-

(i) Material Being Used in Restoration :- Brick Bat

(ii) Equipment/Tools Being used in Restoration Work :- Tractor with bully, JCB.

(iii) Restoration Length

In Open Area - 26.00 m

In Habitation Area :-

B. For Bridge (Size Of Bridge/Culvert)

1. Damage Location/Chainage :-

2. No. Span Damage :-

3. Length of Span :-

4. Nature of Damage (Pier/Abuttment/
Wing Wall/Approach Road Damage)

5. Details of Restoration :-

(i) Material Being Used in Restoration :-

(ii) Equipment/Tools Being used in Restoration Work :-

(iii) Restored Length :-

Overall Grade of restoration Work (Satisfactory/Unsatisfactory) :-

Satisfactory.

Signature Of Inspection
(Official Seal)

असंबद्ध कार्यपालक अभियंता
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, पूर्णियाँ