INSPECTION REPORT FOR MO	
Name of PIUs: - R.W.D., WORKS DIVISION.	- JAGDISHPUR
Name of Plack: Chairpip	
Name of Road :- BARISAWAN ME MAHTHIN MAI (BAJA	ME PUL KE PAHUNCH PATH:
A. For Road	
1. Damage Location/Chainage :- 0.000 KM , 0.31	OKM
2. Damage Length :-	
3. Nature of Damage (Length Wise)	(i) Breach :-
	(ii) Crust Damage :- 55 M
	(iii) Only Flank Damage :- 2 00 M
Where traffic Fully/ Partially obstructed:- Partially	obstructed
1 Details of Restoration :-	
(i) Material being used in restoration works:- Bamboo,	Sand Bag, Brick Bats, Rubbish
(ii) Equipment/ Tools being used in restoration works :- Re	oller, JCB.
(iii) Restored Length 2 55 M	In Open Area:- 255 M
	In Habitation Area :-
(iv) Restoration work done in habitation area give reason :-	Queening .
B. For Bridge (Size of Bridge/ Culvert)	
(1) Damage Location/ Chainage :-	
(2) No. of Span Damage :-	
(3) Length of Span :-	
(4) Nature of Damage (Pier/Abutment/	N.A.
Wing Wall/Approach Road Damage) :-	
(3) Details of Restoration :-	
(i) Material being used in Restoration :-	
(ii) Equipment/ Tools Being Used In Restoration Works :-	
(iii) Restored Length :-	

