

INSPECTION REPORT FOR MOTORABLE WORK

Name of PIUs :- E.E Work Div. Bishanjanj-1

Name of Block/Road :- Bishanjanj/PMUSY Road In Paschim Tola to Bestadangi

A. For Road

1. Damage Location/Chainage :- ch. 180 M

2. Damage Length :- 27.20 M

3. Nature of Damage (Length Wise) (i) Breach :-
(ii) Crust Damage :- 27.20 M
(iii) Only Flank Damage :-

Whether traffic fully/Partially obstructed :- Traffic Partially obstructed

B. Details of Restoration :-

i) Material Being Used in Restoration :- Brick bats

ii) Equipment/Tools Being Used in Restoration Works :- Tractor

iii) Restored Length
In open Area :- 27.20 M
In habitation Area :-

iv) If Restoration work done in habitation Area give Reason :-

B. For Bridge (Size of Bridge/Culvert)

1) Damage Location/Chainage :-

2) No. of Span Damage :-

3) Length of Span :-

4) Nature of Damage (Pier/Abutment/
wing Wall/Approach Road Damage) :-

5) Details of Restoration :-

6) Material Being Used in Restoration :-

7) Equipment/Tools Being Used in Restoration Works :-

8) Restored Length :-

Overall Grade of Restoration work (Satisfactory/Unsatisfactory) :-

Ch
12/11/24
2/14

12/11/24
AE

Signature of Inspector
(Official Seal)