

INSPECTION REPORT FOR MOTORABLE WORK

Name of PIUs :- E. E Work divn. Kishanganj-1

Name of Block/Road :- Kishanganj/ PWD Road. In Bourni Basti to Lokadanga

A. For Road

1. Damage Location/Chainage :- Ch. 80 M, 135 M, 365 M, 1050 M

2. Damage Length :- 96.70 M

3. Nature of Damage (Length Wise)

(i) Breach :-

(ii) Crust Damage :-

(iii) Only Flank Damage :- 96.70 M

whether traffic fully/Partially obstructed :- Traffic Partially obstructed

4. Details of Restoration :-

(i) Material Being Used in Restoration :- Brick bats, earth filling

(ii) Equipment/Tools Being Used in Restoration Works :- Tractor

(iii) Restored Length

In open Area :- 96.70 M

In habitation Area :-

(iv) If Restoration work done in habitation Area give Reason :-

B. For Bridge (Size of Bridge/Culvert)

1) Damage Location/Chainage :-

2) No. of Span Damage :-

3) Length of Span :-

4) Nature of Damage (Pier/Abutment/
wing Wall/Approach Road Damage) :-

5) Details of Restoration :-

6) Material Being Used in Restoration :-

7) Equipment/Tools Being Used in Restoration Works :-

8) Restored Length :-

Overall Grade of Restoration work (Satisfactory/Unsatisfactory) :-

Signature of Inspector
(Official Seal)

12/11/24
a

12/11/24
A