

Inspection Report for Flood Damage Work

1. Name of PIUs : RWD Kishangarh-1
2. Name Of Block / Road : Mahua Se TO7 under Kochadhaman Block.

A. For Road

1. Damage Location / Chainage : .
2. Damage Length : - 0.075 Km
3. Nature Of Damage : Flaking B/D
4. Details Of Restoration :
i) Material Being Used In Restoration :: Bricks etc.
ii) Equipment / Tools Being Used In Restoration Works :
iii) Procedure Taken Up In Restoration Works : Manual.
iv) Restored Length :

B. For Bridge

1. Damage Location / Chainage :
2. Damage Length :
3. Nature Of Damage :
4. Details Of Restoration :
i) Material Being Used In Restoration :
ii) Equipment / Tools Being Used In Restoration Works :
iii) Procedure Taken Up In Restoration Works ::
iv) Restored Length :

[Handwritten signature]
12/11/24

[Handwritten signature]
12/11/24
AE

[Handwritten signature]
Signature of Inspector
(official seal)