

## INSPECTION REPORT FOR MOTORABLE WORK

Name of PIUs :- E.E. ROAD WORK D.V.N. Krishnangam 1

Name of Block/Road :- Kochadhaman, Restoration work for Repair of Road breaches  
for motorability in Nadi Tola to PMBBY Road

### A. For Road

1. Damage Location/Chainage :- Ch. 200M.

2. Damage Length :- 59.0M

3. Nature of Damage (Length Wise) (i) Breach :-  
(ii) Crust Damage :- Under crust damage.  
(iii) Only Flank Damage :- Flank damage.

whether traffic fully/Partially obstructed :- Partially obstructed

### 4. Details of Restoration :-

(i) Material Being Used in Restoration :- Brick bats Used.

(ii) Equipment/Tools Being Used in Restoration Works :- Tractor

(iii) Restored Length  
In open Area :- 59.0M.  
In habitation Area :-

(iv) If Restoration work done in habitation Area give Reason :-

### B. For Bridge (Size of Bridge/Culvert)

1) Damage Location/Chainage :-

2) No. of Span Damage :-

3) Length of Span :-

4) Nature of Damage (Pier/Abutment/  
Wing Wall/Approach Road Damage) :-

### 5) Details of Restoration :-

(i) Material Being Used in Restoration :-

(ii) Equipment/Tools Being Used in Restoration Works :-

(iii) Restored Length :-

Overall Grade of Restoration work (Satisfactory/Unsatisfactory) :-

12.11.24  
JE

Signature of Inspector  
(Official Seal)