

Inspection Report for Flood Damage Work

1. Name of PIUs : R.W.D Kishanganj-1
2. Name Of Block / Road : LO 46 - TOS to Dharhar under Bahadurgang Block.

A. For Road

1. Damage Location / Chainage :
2. Damage Length : 0.120 KM
3. Nature Of Damage :
4. Details Of Restoration :
i) Material Being Used In Restoration :: Bamboo, Local Sand, Bricks bats
ii) Equipment / Tools Being Used In Restoration Works : ~~Manual~~ Tractor, Bamboo piling Machine
iii) Procedure Taken Up In Restoration Works : Manual
iv) Restored Length : 0.120 KM
- ~~0.090 KM~~

B. For Bridge

1. Damage Location / Chainage :
2. Damage Length :
3. Nature Of Damage :
4. Details Of Restoration :
i) Material Being Used In Restoration :
ii) Equipment / Tools Being Used in Restoration Works :
iii) Procedure Taken Up In Restoration Works ::
iv) Restored Length :

Sharma
12/11/24

Sharma
12/11/24
AC

Sharma
12/11/24
Signature of Inspector
(official seal)