INSPEC	CTION REPORT	FOR MO	OTORA	BLE WORK	
Date: - 26/11/24					
1 Name of PIUs:-	Priy	Priyaranjan Das (Executive Engineer Saharsa)			
Name of Block/Road :-				Paswah	
A. For Road					
1 Damage Location/Chainage :-	0.63 KM, 0.8 1.63 KM, 1. 293	25 KM	, 0.88	OKM, 0.9.	SOKM
2 Damage Length :-	293	mt.			
3 Nature of damage	(i) Breach :-	293			
(Length Wise) :-	(ii) Crust Diama	nge :-			
	(iii) Only Flank	Diamage:-			
Whether traffic fully/Partial		Fully	obstructed		
4 Details of Restoration Works :	-				
i Material being used in Resto			Brick Bat & San	ıd	
ii Equipments/Tools being used in Restoration works:-				or,JCB Machine	
iii Restored Length:-		In open A		293	mt.
			tion Area:-		mt.
iv If Restoration work done in H	ion:-		N/A		
B. For Bridge					,
1 Damage Location/Chainage:-		N/A			
2 Damage Length :-		N/A			
3 Nature of damage :-			N/A		
4 Details of Restoration Works :-			N/A	-	
i Material being used in Restortion works:-			· N/A		
ii Equipments/Tools being used in Restoration works :-			N/A		
iii Procedure taken up in Restorat		N/A			
iv Restored Length :-			mt.		
	(C. + C TT . + C	town). Cati	of not over		
Overall Grade of Restoration work (Satisfactory/Unsatisfactory):- Satisfactory					
				ENewet	nspection(Official Seal)  was pegitoger  rks Department  vision,Saharsa