INSPECTION REPORT FOR MOTORABLE WORK

Name of PIUs:- Svolhir kumer.
Name of PIUs: - Svalhir Fumer. Name of Block/Road: - Barray Rwo Road Shuriyali to Sam
A. For Road 1. Damage Location/Chainage: CADA, S W, CH, 450 CH, 950 W
2. Damage Length:- 12 4-5 w
3. Nature of Damage (Length Wise) (i) Breach:-
(ii) Crust Damage :-
(iii) Only Flank Damage:- 124.5
whether traffic fully/Partialiy obstructed:-
4. Details of Restoration:
(i) Material Being Used in Restoration:- Brides Server Works:- Treatment of the Company of the C
(ii) Equipment/Tools Being Used in Restoration Works:
(iii) Restored Length 124.5 w In open Area:- 124.5 w
In habitation Area:
(iv) If Restoration work done in habitation Area give Reason:-
B. For Bridge (Size of Bridge/Culvert)
(1) Damage Location/Chainage:-
(2) No. of Span Damage:-
(3) Length of Span:-
(4) Nature of Damage (Pier/Abuttment/
Wing Wall/Approach Road Damage):-
(5) Details of Restoration:-
(i) Material Being Used in Restoration:-
(ii) Equipment/Tools Being Used in Restoration Works:-
(iii) Restored Length:-
(III) Restored Length
Overall Grade of Restoration work (Satisfactory/Unsatisfactory):-
Overall Grade of Restoration work (Satisfactory)
Lahil.
Signature of Inspector
Signature of Inspector (Official Seal)

AF