

INSPECTION REPORT FOR MOTORABLE WORK

Name of PIUs :- Vikas Kumari EE RWD Agency

Name of Block/Road :- Singarpur, Mulohu, House of Mahon Sahani
SH-74 Agency, Singarpur

A. For Road

1. Damage Location/Chainage :- 620m

2. Damage Length :- 21 m

3. Nature of Damage (Length Wise) (i) Breach :- 21 m
(ii) Crust Damage :-
(iii) Only Flank Damage :-

whether traffic fully/Partially obstructed :- fully obstructed

4. Details of Restoration :-

(i) Material Being Used in Restoration :- Brick Bats, Sand Bags, Bamboo

(ii) Equipment/Tools Being Used in Restoration Works :- JCB, Tractor with Trolley

(iii) Restored Length In open Area :- Open Area
In habitation Area :-

(iv) If Restoration work done in habitation Area give Reason :-

B. For Bridge (Size of Bridge/Culvert)

(1) Damage Location/Chainage :-

(2) No. of Span Damage :-

(3) Length of Span :-

(4) Nature of Damage (Pier/Abutment/
Wing Wall/Approach Road Damage) :-

(5) Details of Restoration :-

(i) Material Being Used in Restoration :-

(ii) Equipment/Tools Being Used in Restoration Works :-

(iii) Restored Length :-

8.935 LAKH

Overall Grade of Restoration work (Satisfactory/Unsatisfactory) :- Satisfactory

28/11/24
re
shaka

28/11/24
re
shaka

Signature of Inspector
(Official Seal)
28.11.24