

INSPECTION REPORT FOR MOTORABLE WORK

Name of PIUs :- E.E, Motihari

Name of Block/Road :- Bangaria / Jatra Link Route No-23 To Janerwa (59)

A. For Road

1. Damage Location/Chainage :- 8.30 km

2. Damage Length :- 58.90 M

3. Nature of Damage (Length Wise) (i) Breach :- ☒ 58.90M
(ii) Crust Damage :- x
(iii) Only Flank Damage :- x

whether traffic fully/Partialy obstructed :-

4. Details of Restoration :-

(i) Material Being Used in Restoration :- Bricks Bats, sand bags

(ii) Equipment/Tools Being Used in Restoration Works :- JCB, Tractor

(iii) Restored Length
In open Area :- open Area
In habitation Area :- x

(iv) If Restoration work done in habitation Area give Reason :-

B. For Bridge (Size of Bridge/Culvert)

(1) Damage Location/Chainage :-

(2) No. of Span Damage :-

(3) Length of Span :-

(4) Nature of Damage (Pier/Abutment/
Wing Wall/Approach Road Damage) :-

(5) Details of Restoration :-

(i) Material Being Used in Restoration :-

(ii) Equipment/Tools Being Used in Restoration Works :-

(iii) Restored Length :-

Overall Grade of Restoration work (Satisfactory/Unsatisfactory) :- Satisfactory

J. Kumar

25/11/24
J.P. 27/11/24

28/11/24
AC

28/11/24
AB

Signature of Inspector
Engineer
Rural Works Department
Works Division, Chakiya