

**Schedule XLV-FORM No. 134**

| Particulars                                           | Details of actual measurement |      |      |      | Contents of area |
|-------------------------------------------------------|-------------------------------|------|------|------|------------------|
|                                                       | No.                           | L.   | B.   | D.   |                  |
| N/w: To NH (Bangra thong) to Kumbhari Bado Raywa Tak. |                               |      |      |      |                  |
| Agency: Gurid Infratech Pvt Ltd.                      |                               |      |      |      |                  |
| Ag. No.                                               | 51 (SRO) / 2014-15            |      |      |      |                  |
| D.O.W.                                                | 16.03.15                      |      |      |      |                  |
| Actual D.O.C.                                         | 19.01.19                      |      |      |      |                  |
| ① Restoration of Rainault —                           |                               |      |      |      |                  |
|                                                       | 25                            | 3.45 | 1.00 | 0.35 | 30.19            |
|                                                       | 20                            | 4.10 | 0.90 | 0.30 | 22.14            |
|                                                       | 30                            | 3.15 | 1.10 | 0.35 | 36.38            |
|                                                       | 32                            | 2.70 | 0.85 | 0.35 | 25.70            |
|                                                       | 15                            | 4.50 | 0.70 | 0.30 | 14.17            |
|                                                       | 35                            | 2.10 | 1.00 | 0.35 | 25.72            |
|                                                       | 40                            | 3.50 | 1.20 | 0.30 | 50.40            |
|                                                       | 32                            | 4.25 | 1.10 | 0.35 | 52.36            |
|                                                       | 30                            | 3.75 | 1.00 | 0.30 | 33.75            |
|                                                       |                               |      |      |      | /                |

|                                |    |      |      |   |                        |
|--------------------------------|----|------|------|---|------------------------|
|                                |    |      |      |   | 290.81 m <sup>2</sup>  |
| ② Maint. of earthen shoulder — |    |      |      |   |                        |
|                                | 25 | 5.00 | 0.70 | — | 87.50                  |
|                                | 15 | 4.50 | 0.90 | — | 60.75                  |
|                                | 30 | 6.00 | 0.85 | — | 153.00                 |
|                                | 40 | 7.00 | 0.80 | — | 224.00                 |
|                                | 35 | 6.25 | 0.90 | — | 196.87                 |
|                                | 24 | 5.40 | 0.85 | — | 110.16                 |
|                                | 20 | 6.00 | 0.80 | — | 96.00                  |
|                                | 27 | 7.50 | 0.75 | — | 157.87                 |
|                                | 17 | 5.15 | 0.85 | — | 74.42                  |
|                                | 35 | 8.00 | 0.90 | — | 252.00                 |
|                                | 32 | 7.50 | 0.80 | — | 192.00                 |
|                                | 30 | 6.25 | 0.85 | — | 159.37                 |
|                                |    |      |      |   | 1757.94 m <sup>2</sup> |

③ Repair to pot holes by  
removal of faulty  
material —

Continuation

| Particulars | Details of actual measurement |   |   |   | Contents of area |
|-------------|-------------------------------|---|---|---|------------------|
|             | No                            | L | B | D |                  |

### Abstract of cost

① Resurber of Poincut -

Qty with TH & R (75)

290.81 m<sup>3</sup> @ R 307.31/m<sup>3</sup> — R 89316:-

② Maint. of earthen Road -

Qty with TH & R (71)

L- 1620.00 m<sup>2</sup> @ R 98.98/m<sup>2</sup> — R 18538:-

③ Repair to pot hole -

Qty with TH & R (76)

L- 168.71 m<sup>2</sup> @ R 322.89/m<sup>2</sup> — R 54437:-

④ The mant of using concrete

Qty with TH & R (76)

L- 168.71 m<sup>2</sup> @ R 331.28/m<sup>2</sup> — R 55905:-

⑤ Patch repair on slabs & kerbs.

Qty with TH & R (76)

L- 168.25 m<sup>2</sup> @ R 305.60/m<sup>2</sup> — R 51570:-

⑥ Mant. of concrete sheet -

Qty with TH & R (76)

6.00 m<sup>2</sup> @ R 866.36/m<sup>2</sup> — R 5198:-

⑦ Maint. of Road kerbs -

Qty with TH & R (76)

2.160 km @ R 865.70/km — R 1870:-

⑧ Cutting of concrete -

Qty with TH & R (76)

12.00 m<sup>2</sup> @ R 75.72/m<sup>2</sup> — R 984:-

⑨ Trimming of grass -

Qty with TH & R (76)

L- 1823.00 m<sup>2</sup> @ R 1.15/m<sup>2</sup> — R 2026

R. 340644:-

Less 8.5% Below — R 28955:-

R 31689:-

  
19/09/23  
32

Continuation