

| Particulars                                                  | Details of actual measurement |    |    |    | Contents of area |
|--------------------------------------------------------------|-------------------------------|----|----|----|------------------|
|                                                              | No.                           | L. | B. | D. |                  |
| 4th year maintenance on A/C Bill.                            |                               |    |    |    |                  |
| ① Restoration of rising cuts with soil etc. all complete job |                               |    |    |    |                  |
| 3 X 12.40 X 1.20 X 0.30                                      |                               |    |    |    | 11.16ms          |
| 2 X 10.50 X 1.20 X 0.30                                      |                               |    |    |    | 6.30ms           |
| 4 X 8.70 X 1.20 X 0.30                                       |                               |    |    |    | 10.44ms          |
| 2 X 10.30 X 1.20 X 0.30                                      |                               |    |    |    | 6.18ms           |
|                                                              |                               |    |    |    | Etis 34.08ms     |
|                                                              |                               |    |    |    | At dlt 32.4ms    |
| ② Making up of berms shoulders etc. all complete job         |                               |    |    |    |                  |
| 2 X 11.70 X 1.20 X 0.30                                      |                               |    |    |    | 28.08            |
| 3 X 10.50 X 2.10 X 0.30                                      |                               |    |    |    | 66.15ms          |
| 2 X 13.30 X 1.90 X 0.30                                      |                               |    |    |    | 50.5ms           |
| 1 X 14.70 X 1.80 X 0.30                                      |                               |    |    |    | 26.46            |
| 2 X 12.70 X 1.75 X 0.30                                      |                               |    |    |    | 44.75ms          |
|                                                              |                               |    |    |    | Etis 189.4ms     |
|                                                              |                               |    |    |    | At dlt 180ms     |
| ③ Maintenance of road signs etc. all complete job            |                               |    |    |    |                  |

Continuation

Continuation CGR 12,228

Scanned with CamScanner