

## Inspection Report of Flood Damage Work

Name of PIUs :- RWD Works Division, Jhanjharpur  
Bewpatti

Name of Block :- Bisli

Name of Road :- Gobind To L034

### A. For Road

1. Damage Location Chainage :- 1.660 Km
2. Damage Length :- 0.010 Km
3. Nature of Damage :- Breach
4. Details of Restoration Works

- i. Materials being used in restoration works:- Brick Bat
- ii. Equipment's/Tools being used in Restoration works:- JCB, Traction
- iii. Procedure taken up in Restoration works:- Brick Bat
- iv. Restored Length:- 0.010 Km

### B. For Bridge

1. Damage Location Chainage :-
2. Damage Length :-
3. Nature of Damage :-
4. Details of Restoration Works

N.A


- i. Materials being used in restoration works:-
- ii. Equipment's/Tools being used in Restoration works:-
- iii. Procedure taken up in Restoration works:-
- iv. Restored Length:-

### C. Requirement Of New CD/ Bridges

- i. Name of Road:-
- ii. Location/ Chainage:-
- iii. Type of CD Work/ Length required:-

N.A

  
Signature of JE/AE/EE

  
Signature  
(Name of Inspection)

E. E. Jay Nagar