

# Inspection Report for Flood Damage Works

Date :-

1. Name of PIUs - Executive Engineer, RWD, ... Shakir Chakia

2. Name of Block - Ghorashan

Name of Road - Lotha Pul to Kasba Sripur

## (A) For Road

1. Damage Location/Chainage :-

2. Damage Length :- 0.200 KM

3. Nature of Damage:- Flood & Heavy Rain

4. Details of Restoration Works:-

(i) Material being used in Restoration works:- Bricks bats

(ii) Equipments/ Tools being used in Restoration works:- Tractor | Trolley | JCB

(iii) Procedure taken up in Restoration works:-

(iv) Restored Length:- 0.200 KM

  
29/11/15

Signature of Inspecting officer  
(Executive Engineer)

R.W.D, W.D.- CHAKIA...