

## INSPECTION REPORT FOR MOTORABLE WORK

Name of PIUs :- R.W.D. work. Div. Bhoagpur.

Name of Block / Road :- खुलतानगंज, "LOSORCD अस्थांज रोड के उभियोंक"

### A. For Road

1. Damage Location / Chainage : 25.203222, 86.687375, ch 4.0 Km to 4.80 Km

2. Damage Length : 180 Mtr

3. Nature of Damage (length wise)	(i) Breach :-	X
	(ii) Crust Damage :-	5 mtr.
	(iii) Only Flank Damage	180 Mtr.

whether traffic fully/Partially obstructed - Partially.

4. Details of Restoration : Sand Bag & Bamboo Filling work

(i) Material Being Used in Restoration : Sand Bag & Bamboo.

(ii) Equipment / Tools being Used in Restoration Works : - Tractor.

(iii) Restored length	In open Area :-	180 Mtr
	In habitation Area :-	- NIL -

(iv) if Restoration work done in habitation Area give Reason :- - NA -

B. For Bridge (Size of Bridge / Culvert) — NA —

1. Damage Location / Chainage :

2. No. of Span Damage :-

3 Length of Span

4 Nature of Damage (Pier / Abutment/Wing wall/Approach Road Damage)

5. Details of Restoration :

(i) Material Being Used in Restoration :

(ii) Equipment / Tools being Used in Restoration Works :

(iii) Restored length	In open Area :-
	In habitation Area :-

Overall Grade of Restoration Work (Satisfactory / Unsatisfactory)

Satisfactory

26/11/2025

A. E.

R.W.D. Subbongam

Signature of Inspector  
(Official Seal)

कार्यपालिक अधिकारी  
ग्रामीण कार्ब विभाग  
कार्य प्रमंडल कलगांव