

INSPECTION REPORT FOR MOTORABLE WORK

Name of PUs :-

EXE ENGINEER RWD BIRAHUL

Name of Block Road :-

KIRATPUR/LO23-LO28 TO PAKKARA

A. For Road

1. Damage Location/Chainage :-

0 - 1000 m, 1000 m to END

2. Damage Length :-

232 m

3. Nature of Damage (Length Wise)

(i) Breach :-

Fully

(ii) Crust Damage :-

—

(iii) Only Flank Damage :-

—

whether traffic fully/Partially obstructed :-

Fully

4. Details of Restoration :-

(i) Material Being Used in Restoration :-

Brick bats / Sand by / Bamboo

(ii) Equipment/Tools Being Used in Restoration Works :-

Tractor, JCB

(iii) Restored Length

In open Area :-

232 m

In habitation Area :-

—

(iv) If Restoration work done in habitation Area give Reason :-

—

B. For Bridge (Size of Bridge/Culvert)

(1) Damage Location/Chainage :-

(2) No. of Span Damage :-

(3) Length of Span :-

(4) Nature of Damage (Pier/Abutment/
Wing Wall/Approach Road Damage) :-

(5) Details of Restoration :-

(i) Material Being Used in Restoration :-

(ii) Equipment/Tools Being Used in Restoration Works :-

(iii) Restored Length :-

Overall Grade of Restoration work (Satisfactory/Unsatisfactory) :-

Ms
30/11/2024

Executive Engineer for

R.W.D. Works Division,

Benipur

Signature