INSPECTION REPORT FOR MOT	ORABLE WORK	
ame of PIUs:- E.E. RWD., BARSOI		- 4
ame of Block/Road: - Rupauli/Tintanga	tole to Chan	han Wasa
For Road		
Damaged Location/Chainage:-		
Damage Length.		A A
Nature of Damage (Length (i) Breach:-		4 - 12 - 12
(ii)Crust Damage:-	~	
(iii) Only Flank Damage:-		3
/hether troffic full /D	- 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1	
/hether traffic fully/Partially obstructed: Details of Restoration:-		
Material Being Used in Restoration:- Bruck	Bats	
) Equipment/Tools Being used in restoration works :-	Bais	
i) Postore III	0.219 K.	M
(i) In open area :-		ne e jen
	1 5	
v) If Restoration work done in habitation Area given Re	eason:-	
. For Bridge (Size of Bridge/Culvert)		
) Damage Location/Chainage :-	ALK	
) No. of Span Damage:-	NI/A	e v
) Length of Span:-	N/A	Branch -
Nature of Damage (Pier/Abuttment/Wing wall/Approch Road	Damage):- N/A	- A
) Details of Restoration:-	1.711	1
Material being used in restoration:-	N/A	The state of the s
Equipment/Tools being used in restoration works:-	AIN	
Restored Length :-	N/A	1 1 1 1 1
verall Grade of Restoration works (Satisfactory/Unsatisfac	stony). Catia las	
verall Grade of Restoration Works (Sunstation yrons anside	A-	ory
William & Road	4	1112 miles
2811114	Signature o	f Inspector
281	(office	•

(office Seal) ि टे डिवरडें कार्यपालक अभियंता ग्रामीण कार्य विभाग, कार्य प्रमंडल, बारसोई, कृदिहार