INSPECTION REPORT FOR MOTORABLE WORK

Name of Block/Road :- PRUPAU	D. BARSOT	10C UT
A. For Road	10 1	THOOF
1. Damage Location/Chainage :-		
2. Damage Length: 0.153	Кн	<u> </u>
	Breach:-	(12)
	Crust Damage :-	,
(iii)	Only Flank Damage :- 🗸	
whether traffic fully/Partialiy obstructed:	-	,
4. Details of Restoration:-	•	9-10-0
(i) Material Being Used in Restoration:-	Brick Bats	
(ii) Equipment/Tools Being Used in Resto	oration Works :-	¥
(iii) Restored Length In c	open Area :-	
In h	nabitation Area :- —	
(iv) If Restoration work done in habitation	n Area give Reason :-	
B. For Bridge (Size of Bridge/Culver	rt)	
(1) Damage Location/Chainage:-	N/A	2 16
(2) No. of Span Damage:-	NIA	- 554
(3) Length of Span:-	NIA	
(4) Nature of Damage (Pier/Abuttment/	N/A	
Wing Wall/Approach Road Damage):-	14/15	
(5) Details of Restoration:-	N/A	
(i) Material Being Used in Restoration:-	NIA	No.
(ii) Equipment/Tools Being Used in Resto	oration Works:- N/A	
AN HOMBINE TOOLS DOING COOK IN THE		

Overall Grade of Restoration work (Satisfactory/Unsatisfactory):- Satisfactory

Signature of Inspector (Official Seal) कार्यपालक अभियंता ग्रामीण कार्य विभाग, कार्य प्रमंडल, बारसोई, कटिहार