


Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
2/10.70 Repair 16 pot holes filled with 75mm thick B.M.					
6 x 4.0 x 1.50 =					36.0 cum
2 x 3.50 x 2.0 =					14.0 cum
				Total	50.0 cum
Hence, 75mm thick B.M.					
= 50.0 cum of 0.075m					
= 3.75 m ³					
4/15.30 Patch repair over pot hole with surface					
Drainage as per condition -					
6 x 4.0 x 1.50 =					36.0 cum
2 x 3.50 x 2.0 =					14.0 cum
				Total	50.0 cum
5/15.30 Patch repair over A.B.D Surface					
6 x 4.0 x 1.50 =					36.0 cum
2 x 3.50 x 2.0 =					14.0 cum
				Total	50.0 cum
6/15.70 mant 16 pipe culvert					02 ms
7/15.70 mant 16 slab culvert					03 ms
8/15.12 cutting or branches & tree					02 ms

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
<u>ABSTRACT OF COST</u>					
1/15.1/ Restoration of Pavements with fresh S.S.U P-49					
75.47 m ² @ 358.87/m ²					27084.2
2/15.2/ making up of 13 cmmy shoulder wide P-49					
419.29 m ² @ 54.16/m ²					22708.2
3/15.30/ Repair of pot holes with 75 mm sm P-50					
3075 m ² @ 10687.98/m ²					40080.2
4/15.300 patch repair over pot hole P-50					
50.00 m ² @ 120.25/m ²					6013.2
5/15.300 patch repair over RT surface P-50					
50.00 m ² @ 107.50/m ²					5375.2
6/15.70 mandrel & work wide page P-50					
02 m ² @ 1067.89/each					2136.2
7/15.70 mandrel & lab cutters					
03 m ² @ 2200.02/each					6600.2
8/15.12 cutting of branches of trees and plants P-50					
02 m ² @ 99.67/each					199.2
Total					110195.2
less 10% below					11020.2
					99175.2
 24/03/23 JE  25/3/23 RE					

Continuation