

5th years maintenance

60

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
1. Name of work: 763 (manuscript se Bernadine) Berna middle school to Chacko to 197489 Chacko Taluk					
2. Name of Agency: Purnam Devi					
3. Agreement No: 61/SBD/2019-20					
4. Actual date of completion: 08-03-2020					
Work done					
① Restoration of earthen cut with soil - elev fill					
5x 30.00 x 1.00 x 0.30 = 45.0					
4x 20.00 x 0.85 x 0.30 = 21.012					
3x 10.50 x 0.72 x 0.32 = 7.258					
1x 9.00 x 0.60 x 0.30 = 1.710					
2x 9.55 x 0.62 x 0.30 = 3.552					
					Qty = 78.532m ³
					Soil Qty = 77.46m ³
② maintenance of earthen shoulder - elev fill					
5x 20.60 x 1.0 = 103.0					
6x 20.90 x 0.85 = 106.59					
7x 18.60 x 0.92 = 119.784					
2x 10.50 x 0.82 = 17.22					
2x 18.60 x 0.72 = 26.784					
3x 10.18 x 0.78 = 23.821					
2x 18.65 x 0.73 = 27.229					
2x 5.962 x 0.50 = 5.962					
					Qty = 430.31m ³

Continuation

P-770.

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
					B.P.R. 17909=00
④ patch repair on already filled pot holes with 75mm w.b.m. 1st. detail					Qty = 96.40 m ² vide TMB page (61)
⑤ 292=55/m ² —					R 28202=0
⑤ maintenance of 1900 pipe culvert double					Qty = 4.0 nos vide TMB page (61)
⑥ 1117=00/each —					R 4468=0
⑥ 1900 maintenance of 2000					Qty = 1.0212m vide TMB page (61)
⑦ 1077=51/km —					R 750=0
⑦ 1900 maintenance of 2000					Qty = 204.20 m ² vide TMB page (62)
⑧ 755=53 m ² —					R 154279=0
					R 265608=00
Less 10.0% below C/I					R 26561=00
					R 239047=00

Continuation