

Dr. McGilly

52

DIVISION


SUB-DIVISION

1435

52
Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
5/2 year maintenance					
Name of work -	Maintenance of road 9701				
	C.D. Work from Hardwar				
	more to P.V. measurement				
	Shivaman taluk				
	M.M.S.S.				
Agency -	Sri N. K. Kulkarni Deo				
Agreement No -	42389/2017-18				
Agreement value	52517.86 = 01				
Date of work bear maintenance start -	21/06/23				
Date of work year maintenance complete -	20/06/23				
Date of measurement -					
(1) Restoration of cancelled bearings					
	with survey measurement of				
	per E/f				
	2x2	8.75	1.125	0.300	11.81 M ²
	2x2	5.42	1.125	0.300	7.36 M ²
	2x	6.85	1.125	0.300	4.62 M ²
	3x	3.51	1.125	0.300	3.65 M ²
					27.34 M ²
(2) making 4 bearings standard					
	stripping the 2x0.85 m				
	from standard per E/f				
	2x2	6.28	1.125		28.26 M ²
	2x2	7.25	1.125		34.87 M ²
	5x	5.85	1.125		32.91 M ²
	4x	4.90	1.125		22.05 M ²
					118.09 M ²
Continuation					

55
Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
	21	6.15	0.400		4.92M ²
	22	6.15	0.600		14.76 M
	23	0.400	0.600		0.96 M
					20.64M ²
					
ABSTRACT OF COST					
STATIONERY AND STATIONERY					
(1/1) Restoration of damaged leaves					
with saddle stitching					
as per E/H					
as per T.M.B.P-52(1)					
	27.134M ²	@	351.00/M ²	Δ	9538.00
(2/2) Making up beyond flaps					
as per E/H					
as per T.M.B.P-52(2)					
	151.88M ²	@	52.66/M ²	Δ	7983.00
(3/3) Repair of pot hole with					
with 75mm B.M. as per E/H					
as per T.M.B.P-53(3)					
	2.64M ³	@	1050.81/M ³	Δ	2782.00
(4/4) Patch repair of pot hole					
with 20mm P.M.C. with					
seal coat type B as per E/H					
as per T.M.B.P-54(4)					
	35.04M ²	@	282.18/M ²	Δ	9882.00
Continuation					Cost - 55382.00