

Sch. XLV-Form No. 134

① Rehabilitation of main				
cable — 20 —				
12	x	4.40	x 1.00 x 0.80 =	15.84
16	x	2.90	x 1.10 x 0.80 =	20.59
9	x	4.60	x 1.05 x 0.80 =	13.04
5	x	4.80	x 0.95 x 0.80 =	6.41
				55.88 m
② Maint. of Southern				
shoulder — 20 —				
2	x	9	x 5.60 x 0.90 =	90.72
2	x	8	x 4.90 x 1.10 =	86.24
2	x	6	x 4.50 x 0.80 =	43.20
2	x	8	x 4.55 x 0.95 =	69.16
2	x	9	x 6.60 x 0.80 =	95.04

Continuation

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Abstract of cost					
① Description of main					
cut - do -					
55.88 m ² - wide - P-64					
@ 402.70/m ² -					5 99782.0
② Maint. of Southern					
Shoulder - do -					
648.00 m ² - wide - P-64					
@ 60.79/m ² -					5 99392.0
③ Patch repair over					
bituminous surface					
do -					
43.18 m ² - wide - P-65					
@ 288.12/m ² -					5 12428.0
④ Maint. of flame pipe					
culvert - do -					
02.00 m ² - wide - P-65					
@ 1182.79/each -					5 9966.0
⑤ Maint. of slab					
culvert - do -					
01.00 m ² - wide - P-65					
@ 9426.45/each -					5 9426.0
⑥ Maint. of road					
Sign - do -					

Continuation

Material used:-

Earthwork	-	152.080 m ³
Emulsion	-	14.00 kg
Ridimen	-	92.00 kg
Stone chips	-	1.165 m ³
Sand	-	0.259 m ³

Slender
05/09/2018
I.E.

Continuation