INSPECTION REPORT FOR MOTORABLE WORK

Name of PIUs :-	RWD, Benipatti
Name of Block/Road :-	Ghoghardiha / flood damage repair of L03 Hasani to Mainahi

A. For Road

1. Damage Location/Chainage :-		
2. Damage Length :-	207 M.	
3. Nature of Damage (Length Wise)	(i) Breach :-	
	(ii) Crust Damage :-	207 M
	(iii) Only Flank Damage :-	207 M
whether traffic fully/Partially obstructed :-		
4. Details of Restoration :-		
(i) Material Being Used in Restoration :-		
(ii) Equipment/Tools Being Used in Restoration Works :-		
(iii) Restored Length	In open Area :-	
	In habitation Area :-	
(iv) If Restoration work done in habitation Area give Reason :-		

B. For Bridge (Size of Bridge/Culvert)

(1) Damage Location/Chainage :-
(2) No. of Span Damage :-
(3) Length of Span :-
(4) Nature of Damage (Pier/Abuttment/ Wing Wall/Approach Road Damage) :-
(5) Details of Restoration :-
(i) Material Being Used in Restoration :-
(ii) Equipment/Tools Being Used in Restoration Works :-
(iii) Restored Length :-

Overall Grade of Restoration work (Satisfactory/Unsatisfactory) :- Satisfactory

A. Kumar

11.11.14
AB

Signature of Inspector
(Official Seal)
Executive Engineer
R.W.D Work Division
Benipatti

ABSTRACT OF QUNTITY (QUANTITY CALCULATION SHEET)

Flood Damage Repair of L03 Hasani To Mainahi

SL. NO.		NO.	LENGTH	WIDTH(Avg)	DEPTH(avg)		QUANTITY	
1.								
	Ch 320 M To 465 M	1	30	(2.2+2.3+1X1.5X2)/2	(1.8+2.2)/2	=	225.000	
		1	30	(2.2+2.3+1X1.5X2)/2	(1.8+2.2)/2	=	225.000	
		1	30	(2.2+2.3+1X1.5X2)/2	(1.8+2.2)/2	=	225.000	
		1	30	(2.1+2.1+1X1.5X3.4)/2	(2.9+3.5+3.8)/3	=	474.300	
		1	25	(2.1+2.1+1X1.5X2)/2	(1.8+2+2.2)/3	=	180.000	
	Ch 660 M To 700 M	1	30	(1.8+1.8+1X1.5X2)/2	(1.2+1.5+1.8)/3	=	131.625	
		1	10	(1.9+1.9+1X1.5X1.35)/2	(1.2+1.3+1.55)/3	=	39.319	
	Ch 740 M To 762 M	1	22	(1.9+1.9+1X1.5X1.3)/2	(1.2+1.3+1.4)/3	=	79.365	
			207			=	1579.609	CuM

AKD 14.11.24
AB

Executive Engineer
R W.D Work Division
Benipatti