FIELD INSPECTION REPORT

Date Of Inspection	16.12.2020	District - Bhojpur	
Division - PIRO, Block - PIRO		Length (km): 2.30 K.m	
Name of the Road:	L077- Tola to Narayanpur		
Scheme/Programme	MAINTENANCE		
Package No.: BR-07R-		Road Id No.:	
Status of the Project :	Ongoing/Completeted/Under Maintenance		
Work is a case of :	New Connectivity/Up gradation/Maintenance		

Sl No.	Parameters to be checked	Remarks
1	**Pavment**	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2	**Cross Drainage**	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3	**Road Furniture**	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4	**Compliance History**	
a)	Status of ATR's & any others	

Overall Rating :		
	Satisfactory (S)	"S"
	Satisfactory but requires Improvement (SRI)	
	Unsatisfactory (U)	

16.12.2020

Name: Sushil Kumar **(Signature)**

Designation Junior Engineer