INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD

Name of Scheme:	Rosera Rural Grmt. to Balka		
Hazards	Flood/Rain		
Division : Rosera	District: Samastipur	Actual Length (in km): 3.000	
Damage Length (in km): 1.000	Damages Location/Chainage:		
Name of Scheme/Programme:	FDR		
Status of Project:	Under Agreement/Out of Agreement		
Sr. No.	Parameters to be Checked in Restoration work		Remarks : (S/U)
1.	Pavement (BT/CC)		
a)	Condition of Surfacing		S
Description of observation :	Good.		
b)	Adequate Thickness of pavement layers constructed		S
Description of observation :	M-SS thickness - 20mm		
c)	Quality of Construction Material Used		S
Description of observation :	Satisfactory.		
d)	Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement , Poor workmanship, etc.		S
Description of observation :	No defect		
e)	Compaction of flanks/ slope & raincuts		
Description of observation :	No Provision		
2	Cross Drainage Structure		
a)	Condition of head walls in Hume pipe culverts		
b)	Condition of Vent Clearance		
C)	Condition of railings/Slab/approach for Bridges		
Description of observation of CD works :	No Provision		
Remark if any:	B.T Work Completed. P.C.C. work in Progress (198m)		

Overall Rating

Satisfactory (S) / Unsatisfactory (U)	U

Name of Officer: Mahesh Pd. Gupta

Designation: EE, RWD, Regional Lab. Purnea

(Signature) 18/07