ग्रामीण कार्य विभाग

Rural Works Department, Govt of Bihar

DETAILD PROJECT REPORT FOR MOTRABLE REPAIRING OF ROAD

F.D.R. PART - MOTRABLE RESTORATION

PMGSY ROAD TO ENGLISH TOLA

DETAILED ESTIMATE OF F.D.R. MOTRABLEREPAIRING ROAD

ROAD LENGTH	0 TO 400
DISTRICT	KATIHAR
BLOCK	MANIHARI
DIVISION	MANIHARI

TOTAL LENGTH OF ROAD		0.400	KM
TOTAL COST OF F.D.R. PART - A		Rs. 2.048	Lacs
ADD G.S.T @ 12%		Rs. 0.246	Lacs
ADD Labour Cess @ 1%		Rs. 0.020	Lacs
ADD Seigniorage Fee @ 10%		Rs. 0.111	Lacs
TOTAL COST OF RESTORATION WORK In Rs.		Rs. 2.425	Lacs

SUBMITTED BY
The Executive Engineer,
Works Division, Manihari

Scanned with CamScanner

प्रतिवेदन

पथ का नाम :- PMGSY Road To English Tola.

पथ की लम्बाई :- 0.400 KM

प्राक्कलित राशि :- 2.425 Lac

वित्तीय वर्ष :- 2021-2022

प्रखंड :- Manihari

प्रस्तुत प्राक्कलन रु० 2.425(दो लाख बयालीस हजार पाँच सौ)

की राशि मे ग्रामीण कार्य विभाग, कार्य प्रमंडल मनिहारी अन्तर्गत मनिहारी प्रखंड के S028 To Banfh Ganga पथ हेतु तैयार की गई है। वर्त्तमान वर्ष 2021 के बाढ एवं अतिवृष्टि के कारण क्षतिग्रस्त एवं पथ को MISपर अपलोड किया जा चुका है, तथा विभागीय निर्देश ग्रामीण कार्य विभाग, बिहार के पत्रांक–मु० अ०–4 (मु०) विविध (कार्य)–23/291/2019–4275/पटना, दिनांक– 22.10.2021 के आलोक में यातायात(Motorable) पुर्नस्थापन किया गया है।

उपर्युक्त प्राक्कलन में क्षतिग्रस्त सड़क के फ्लैंक/सरफेस को Bricks basts से भरकर आवागमन चाक किया गया है एंव सड़क पर होने वाली दुर्धटना को रोका गया है।

प्रक्तुत प्राक्कलन ग्रामीण कार्य विभाग, कार्य अंचल पुर्णियाँ द्वारा प्राप्त कोटेशन के न्युनतम दर पर तैयार किया गया है, प्राक्कलन की स्वीकृति जनहित में अति आवश्यक हैं।

25/11/24	25/11/24	
कनीय अभियंता	सहायक अभियंता	कार्यपालक अभियंता
ग्रामीण कार्य विभाग	ग्रामीण कार्य विभाग	ग्रामीण कार्य विभाग
कार्य प्रशाखा, मनिहारी	कार्य प्रशाखा, मनिहारी	कार्य प्रमंडल, मनिहारी

Scanned with CamScanner

(12)

Inspection Report for flood damage work

Date:

1.Name of PIUs- RWD Manihari

2.Name of Block/Road- Manihari | Pmgsy road to Englishtola.

A.For Road

1.Damage Location/Chainage : At different clevinese.
2. Damage Lengh : 82.50m
3.Nature of Damage : Shoulder
4.Details of Restoration :
i Material being used in Restoration : Brick Bats.
ii Equipment/Tools being used in Restoration works: Tractor
iii Procedure taken up in Restoration works :
iv Restored Length : 82.50m.

B. For Bridge

1.Damage Location/Chainage :
2. Damage Lengh :
3.Nature of Damage :
4.Details of Restoration :
i Material being used in Restoration :
ii Equipment/Tools being used in Restoration works:
iii Procedure taken up in Restoration works :
iv Restored Length :

25/11/24

Signature of JE/AE/EE

25/11/24

Signature

(Name of Inspector)

Scanned with CamScanner

GENERAL ABSTRACT OF COST FOR MAINTENANCE OF ROAD

NAME OF ROAD : PMGSY ROAD TO ENGLISH TOLA

DISTRICT KATIHAR

DIVISION MANIHARI

BLOCK MANIHARI

LENGTH OF ROAD (IN KM) 0.400

Sl. No.	ITEM OF WORK	AMOUNT (LAKHS)
1	EARTH WORK	0.000
2	HUME PIPE	0.000
3	BRIKCK BAT	2.048
4	SAND BAGS	0.000
5	BAMBOO WORK	0.000
6	STEEL DRUM SHEET	0.000
	TOTAL COST OF PROJECT =	2.048
	Add G.S.T. @ 12%	0.246
	Add Labour Cess @ 1%	0.020
	Add Seigniorage Fee @ 10%	0.111
	Total Cost of Restoration Work =	2.425

25/11/24
J.E.
RWD

25/11/24
A.E.
RWD

25/11
E.E.
RWD

Technically Sanction for Rs. 2.425 Lac (Rs. .....
Crore..... TWO ..... Lac..... forty two .....
Thousend..... five ..... Hundred. .....)Only

Superintendent Engineer
Rural Works Department
Works Circle, Purnea

Scanned with CamScanner