Inspection Report of Flood Damage Work

Name of PIUs :- RWD Works Division, Jhanjharpur

Name of Block :- _Jhanjharpur_

Name of Road :- _chanauragany To majhaura. (Sisauni Grav_
se Majhaura Hote hue chanauraganj)

A. For Road

1. Damage Location Chainage   :-
2. Damage Length   :- _425.00 m_
3. Nature of Damage   :-
4. Details of Restoration Works
    - i. Materials being used in restoration works:- _Boulder beats_
    - ii. Equipment's/Tools being used in Restoration works:- _Tractor_
    - iii. Procedure taken up in Restoration works:- _769, 895 m)_
    - iv. Restored Length:-

B. For Bridge

1. Damage Location Chainage   :-.
2. Damage Length   :-
3. Nature of Damage   :-
4. Details of Restoration Works

    - i. Materials being used in restoration works:-
    - ii. Equipment's/Tools being used in Restoration works:-
    - iii. Procedure taken up in Restoration works:-
   - iv. Restored Length:-

C. Requirement Of New CD/ Bridges

i. Name of Road:-

ii. Location/ Chainage:-

iii.Type of CD Work/ Length required:-

Signature of JE/AE/EE

Signature
(Name of Inspection)

Chanaurgganj to Maghaura FDR

Shedule XLV Form No. 134.

Executive Engineer
Rural Works Department
Works Division, Jhanjharpur

————————————— DIVISION

JHANJHARPUR

————————————— SUB-DIVISION

315

Measurement Book

Name of Work–
Situation of Work–
Agency by which work is executed–
Date of Measurement–
No. and date of agreement

(These four lines should be repeated at the commencement
of the measurement relating to each work)

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
	CH - FDR				

Name of work :- Motorable of road
damaged by flood from
Mashaura to chanauragani

Agency :-

woolk door

Measurement taken as per DPR

① Providing and filling
brick bats in ditches
damaged embankment
including cost of brick
bats & lab - - - - - -

1x	14 x	3.50	x0.60	=	29.40m
1x	55 x	4.25	x0.30	=	70.125
1x	40 x	3.50	x0.50	=	70.00 "
1x	45 x	3.60	x0.60	=	97.20 "
1x	33 x	3.50	x0.65	=	75.08 "
1x	28 x	3.75	x0.50	=	52.50 "
1x	22 x	3.50	x0.75	=	57.75 "

Continuation

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
	1 X 23 ×	3·60	X 0·30	= 24·84
	1 X 53 ×	3·50	× 0·45	= 83·48
	1 X 18 ×	3·60	× 0·40	, 25·92
	1 X 15 ×	3·50	X 0·30	= 15·75
	1 X 10 ×	3·90	X 0·40	= 15·60
	1 X 5 ×	3·50	× 0·25	= 4·38
	1 X 45 ×	3·70	× 0·55	= 91·58
	1 X 19 ×	3·95	× 0·75	= 56·29
			Total		769·895 M³

10·6·22
J. E.

Abstract of cost

① P/N and filling brick bats in ditches/damaged embank
ronical

769·895 M³ Qty vide TMA P/2

769·895 M³ @ 2004·96/M ₹ 1543609=

Add 12% GST ₹ 185233=00

Add 1% L.C ₹ 15436=00

Add 5% S. Fee ₹ 79453=00

₹ 1823731=00

10·6·22
J. E.

Continuation